BCAG - Hazardous Spill Report Site: Plant 2

DATE: 12/22/98

BY: Steve McLaughlin
The shop is responsible for completing the following information:
Date of Spill:12/22/98 Time of Spill:1:15 AM □ PM 🛚 Location of Spill:2-83.1 A-1-1
Material Spilled: Cooling Tower water_Estimated Quantity:10 gallons_ Contained on Site <u>yes</u> Release to Soil <u>Air</u> Water
Cause of Spill: Water that was not drained from the Baltimore Cooling Tower on the 2-83 roof had frozen in the pipes. Consequently the pipes froze and broke. The heat of the sun thawed the water in the frozen pipes and drained down the side of the bldg. to the ground below and into the storm drain. A Red Customer Service HVAC employee that found this incident covered the storm drain in the area, reported the incident, opened a Service Request 124734, and called me stating that there was glycol on the ground.
Actions taken and by whom: The storm drain was properly covered by the Red Customer Service Team preventing any additional water from entering the drain. CORE Facilities and Environmental were notified and escorted to the site of the incident. This group made an inspection and it was then determined that the liquid was water from the cooling tower and not glycol as originally reported. The incident was reported to Marty Martinson, Director of West Region Facilities.
Equipment Error: □Yes □No Operator Error: □Yes □No Process Error: □Yes □No Other Cause: Cooling tower pipes were not completely drained
What, if any, follow-up action is required: CORE Facilities had the action to repair the broken pipes. Spill reported by: Steve McLaughlin Organization: 6-8WHJ
Phone Number: 206-655-7770 Time: 1:15 AM PM Mail completed report to Environmental Affairs at M/S 63-41. Questions, contact Yvette Barnett at 237-9263 or pager number 982-1880.
Environmental Affairs will notify the regulatory agencies. Additionally they will complete any follow-up incident reports.
Agency Name: Time:AM □ PM □ Spill Report Number:Contact Person: